

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+020**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+050**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+070**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+090**

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+200**

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+450**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+500**

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 6
--------------------------	--------------------------------------	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+700**

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 7
--------------------------	--------------------------------------	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+870**

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 8
--------------------------	--------------------------------------	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 0+950**

LOKASI : **STA 0+980**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 9
--------------------------	--------------------------------------	-------------------------------	---	---------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 1+000**

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 10
--------------------------	--------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 1+190**

LOKASI : **STA 1+200**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 11
--------------------------	--------------------------------------	-------------------------------	---	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



30/10/25 10:45:17
7,221672S 109,829745E
Kabupaten Banjarnegara
#Ruas V. 33 Ratamba - Mramen
#STA 1+300
#Survei Jalan #DPUPR Kab Banjarnegara



30/10/25 10:46:44
7,221542S 109,830617E
Kabupaten Banjarnegara
#Ruas V. 33 Ratamba - Mramen
#STA 1+400
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+300**

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



30/10/25 10:47:48
7,221217S 109,831347E
Kabupaten Banjarnegara
#Ruas V. 33 Ratamba - Mramen
#STA 1+500
#Survei Jalan #DPUPR Kab Banjarnegara



30/10/25 10:48:52
7,221512S 109,832275E
Kabupaten Banjarnegara
#Ruas V. 33 Ratamba - Mramen
#STA 1+600
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+500**

LOKASI : **STA 1+600**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 1+700**

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 1+900**

LOKASI : **STA 1+910**


KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
V. 33	Ratamba - Mramen		MELDA & DAHLAN	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Ratamba - Mramen



LOKASI : **STA 1+950**

LOKASI : **STA**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN
LEBAR PERKERASAN
TYPE PERKERASAN

NO. RUAS V. 33	NAMA RUAS Ratamba - Mramen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 16
--------------------------	--------------------------------------	-------------------------------	---	----------------------